




VACUUM PUMP AND FITTINGS

Vacuum cleaners, refrigeration compressors, air conditioning pumps, and other devices may be used to create a vacuum pump for the woodturning lathe. This plan shows some suggested sizes and a suggested order for assembly.



Vacuum pump should move about 9 m³/hr. A smaller pump can be improved by the addition of reserve tanks.